DMM Application
Installation Manual

This manual contains instructions how to install the special software "DMM Application" for MODEL 8241.

1. Introduction

● Interface
 This instrument is equipped with a USB interface.
 Specifications of USB: Ver.1.1 (Reference)
 Following can be done by USB communication.
 ・ Downloading files in the internal memory of the instrument to a PC.
 ・ Real-time data reception
● Software
 DMM Application
● System Requirements
 ・ OS (Operation System)
  Please check on our website.
 ・ MEMORY
  64Mbyte or more
 ・ Display
  1024×768 dots, 65536 colors or more
 ・ HDD (Hard-disk space required)
  10 Mbyte or more
● Communication Commands
 For details on commands, refer to the instruction manual for MODEL 8241.
● Trademark
 ・ Windows® is a registered trademark of Microsoft in the United States.

The latest software is available for download from our website.
www.kew-ltd.co.jp

KYORITSU ELECTRICAL INSTRUMENTS WORKS, LTD.

---

2. DMM application installation

(1) The followings should be checked before installing this application.
 ・ To prepare your system for installation, please close all open programs.
 ・ Be sure NOT to connect DMMs until the installation completes.
 ・ Installation shall be done with Administrator right.

(2) Please access our website (www.kew-ltd.co.jp/en/) and go to "Download" and then "Software" and download "DMM Application" according to the instructions described on the page.

(3) When download completes, click "setup_ENG.exe" and click "Next".

(4) Read through and understand the License Agreement and click "I accept….", and then click **Next**.

(5) Confirm the information on installation, and then click **Install** to start installation.

---

(6) Click **Finish** when "InstallShield Wizard Complete" dialog box appears.

---

3. USB driver Installation

(1) Please access our website (www.kew-ltd.co.jp/en/) and go to "Download", "Software" and then "DMM Application". Download "USB Device Driver" according to the instructions described on the page.

(2) Connect MODEL 8241 and your PC with the supplied USB cable. Right-click Start button and then Device Manager.

---

(3) Click Other devices and right click on "MODEL8241". Then click Update Driver.

(4) Select" Browse my computer for drivers".

---

(5) Check the box for "Include subfolders", and then click "Browse".

(6) Select the "DRIVER" folder in the "MODEL8241 USBDriver" downloaded at step (1) and click "OK".


---

(7) When the following confirmation message appears, click Install.

(8) Installation is completed when the wizard says, "Windows has successfully updated your driver software".
Click Close.

---

(9) The following two icons will appear in Device Manager when the driver is successfully installed.

---

4. USB driver un-installation

If USB driver installation got aborted and unable to complete re-installation, follow the procedures below and remove the USB driver first. Then restart the whole installation process.

(1) Connect your PC and MODEL8241 with a USB cable.

(2) Right-click Start button, and then click Device Manager.

(3) Click Other devices and right click on MODEL8241.

(4) Click Uninstall to uninstall the USB driver.

(5) Disconnect the USB cable connected to the PC once, and connect it again.

(6) When "Found New Hardware Wizard" window appears, please refer to and follow the procedures described in "3.USB driver installation" to complete installation.

MEMO

KYORITSU ELECTRICAL INSTRUMENTS WORKS, LTD.

2-5-20,Nakane, Meguro-ku, Tokyo, 152-0031 Japan
Phone: +81-3-3723-0131
Fax: +81-3-3723-0152
Factory: Ehime,Japan

www.kew-ltd.co.jp