When purchasing another models in Logger series and installing the driver on Windows 2000/XP, installation of disk may be demanded. In such a case, install the driver contained in the KEW LOG Soft2 (ver.2.06 or earlier).

If you lost the CD, please download the driver for "Windows2000/XP/Vista" from our Software download site: Http://www.kew-ltd.co.jp/en/download/index.html

*Label stuck on the case for KEW LOG Soft2 shows its version.

Insert the CD of ver.2.06 or earlier and install the driver.

Following window appears when installing the driver contained in the KEW LOG Soft2 ver.2.07 or later.

When installation of a disk is demanded:
Please follow below instructions to install the driver.

Installation procedure
1) Click "OK" when following window appears.

CD/ DVD drive and disk name depend on your PC environment.

2) Click "Browse..." when following window appears.

3) Then a window showing the file location is displayed.

4) Unzip the self-extracting file and select "FTD2XX" contained in the new folder. Then click "Open".


5) Then click "OK" when following message appears.

6) Then click "Yes" when following message appears.

Confirm File Replace

Source: e:\FTD2XX.dll.
Target: C:\WINDOWS\system32\FTD2XX.dll.

The target file exists and is newer than the source.

Overwrite the newer file?

[Yes]   [No]   [No to All]

The following window appears.

Found New Hardware Wizard

Please wait while the wizard installs the software...

KEW LOGGER 5010/5020

Setting a system restore point and backing up old files in
case your system needs to be restored in the future.

[< Back]   [Next >]   [Cancel]

7) Now installation completes. Click "Finish" to finish the installation.

Found New Hardware Wizard

**Completing the Found New
Hardware Wizard**

The wizard has finished installing the software for:

KEW LOGGER 5010/5020

Click Finish to close the wizard.

[< Back]   [Finish]   [Cancel]

* Windows® is the registered trademark of Microsoft in the United States.