


Display range and guaranteed accuracy range for each Current Range are as follows.



Sensors: 8141/42/43 and 8146/47/48 cannot be used for power measurements.